



Nr	Gerst	Lengd	3/8" Stüben
1	V 55	900	A-B
2	1 5 1/2	1000	A-B
3	1 4 1/2	2000	A-B
4	1 4 1/2	3000	A-B
5	V 50	1000	A-B
6	V 50	900	A-B
7	V 50	800	A-B
8	V 50	700	A-B
9	V 50	600	A-B
10	V 50	500	A-B
11	V 50	400	A-B
12	V 50	300	A-B

Alles lazin i veggjen
 I. hat
 E. H. ... Hafizof;
 Hitze ... 1. Apr. 12
 ...