



Sambýkkt þarftu
13 OKT. 2001
Byggingarfulltrúginn í Hæðinni
Eh. Sigurbjartur Halldórsson

Borgir Eiríksson
Borgir Eiríksson 111038-3259

ÚTG.	DAGS.	TEIKN.	BREYTT	YFIRF.	SAMB.	ÚTG.	DAGS.	TEIKN.	BREYTT	YFIRF.	SAMB.	TEIKN. NR.	3.01	 Bíldshöfði 12 112 Reykjavík Sími: 557 5200 Fax: 557 5201	GAUKSÁS 14-16 BURDARVIRKI SÖKKLAR	ÚTG. B
		B	11.10.01	Súla og snió F		A	18.07.01	Sníó E og fl.								