



Gólfkóli er héc settur 0,0 en ex. aftr
 hédarmærkjakerli Hafnarfjarðar
 Elni og frágangur sé í samræmi
 Holræsareglugærd Hafnarfjarðar

Óseyrarbraut 9-11 Hafnarfjörð	Gunnar Erlendsson Tæknifræðingur Sími 4 21 75	
Holræsarlögn	Mælikv 1:100	Teikn