


Athuga skal staðsetningu lagna með tilliti til burðarbita í gólfi.


K = 26.75

Grunnmynd frárennsli
2 hæð. M = 1 : 50

Skýringar sjá teikn. nr.: F-1.00



Verkefni. LÓUHRAUN 5, HAFNARFJÖRDUR

 GRAVÍS Kaplahraun 15, 220 Hafnarfjörður.
sími.: 555 3783 fax.: 555 2873 GSM 899 0423 & 699 3781
Kt.: 65 03 98 - 3519 VSK nr.: 57639

Dags.: 16.02.00	Verkpáttur.	Skrá nr.:
Kvarði.1 : 50		Verk nr.: 006.00
Teikn.: P.A.		Teikn nr.:
Samp.:		F-1.01
Lögg.: BFI / TFI	I-914-19.02.70 I-852-22.03.78	Sími-fax 568 1673

ÞORGILS AXELSSON BFI / TFI. STEFÁN JÖRUNÐSSON TFI.
14 12 42 - 4829 (GSM 864 1673) 23 01 45 - 7099 (GSM 699 0423)

Stefán Jörundsson